

Task performed	Risk	PPE required
Dry sanding of paints/fillers	Inhalation of poison dust, Flying particles, Drop injury (feet), skin contact.	Dust mask, Safety goggles, Overalls, Steel caped shoes, Latex gloves.
Cleaning a panel with solvent	Splashes, inhalation of solvent vapour, skin contact, Drop injury (feet)	Carbon activated mask, Safety goggles, solvent proof gloves, Steel caped shoes, Overalls.
Mixing paints	Splashes, inhalation of solvent vapour, skin contact, Drop injury (feet)	Carbon activated mask, Safety goggles, latex gloves, Steel caped shoes, Overalls.
Spraying 2K paints	Splashes, inhalation of solvent and mist vapour, skin contact, Drop injury.	Air fed full face mask, latex gloves, Steel caped shoes, painting overalls.
Spraying 1K paints	Splashes, inhalation of solvent vapour, skin contact, Drop injury (feet)	Carbon activated mask, Safety goggles, latex gloves, Steel caped shoes, painting overalls.
Gun cleaning	Splashes, inhalation of solvent vapour, skin contact, Drop injury (feet)	Carbon activated mask, Safety goggles, solvent proof gloves, Steel caped shoes, Overalls.
Paint stripping	Splashes, inhalation of solvent vapour, skin contact.	Carbon activated mask, Safety goggles, solvent proof gloves, Steel caped shoes, Overalls.
Polishing	Cuts, spatter, Machine entanglement with clothes	Dust mask, Safety glasses, Overalls, Steel caped shoes, cut resistant gloves.