

November 2015

This data sheet supersedes all previous issues

Always use correct Personal Protective Equipment

RAPID FILLER

Description



A rapid curing 2-pack Acrylic Urethane Primer Filler/Primer Surfacer that is free sanding with excellent filling properties and gloss hold under 2K topcoats and Acrylic Lacquers. It can be used as a primer filler or primer surfacer by adjusting the amount of RALI 400 Reducer used.

Products



Product Type: Acrylic Urethane

Colour: Grey

Pot Life: 1 hour with RALI GP Hardener

Induction Time:

Density: 1.5 kg/L approx **Recommended DFT:** 50-70 microns

Theoretical Coverage: 6.0-8.4 m²/litre @ 50-70 microns DFT.

Properties



VOC: 498 g/L unthinned

Volume Solids: 41.6% approximately unthinned

Recoat-ability: Self Recoat: Between 20 minutes and 50 minutes

Topcoat: After sanding

Dry Time @ 20°C: Tack free: 30 minutes RALI GP Hardener

Handle: 1 hour using RALI GP Hardener Dry to sand: 2½ - 3 hours @ + 20°C

Force Dry @ 60°C: 30 minutes after 5-10 minutes flash off. Sand when cool.

Substrates



Rapid 2K Filler can be applied over correctly prepared:

- Aged and fully cured Automotive finishes including Acrylic
- Lacquers and clear over base systems.
- Steel
- Polyester body fillers
- Aluminium (apply first 81A Two-Pack Etch Primer-refer Data Sheet)
- Galvanised steel (apply first 81A Two-Pack Etch Primer)
- Wood and MDF Board Composites
- Glass Reinforced plastics (Fibreglass)
- Plastic Bumpers

No warranty either expressed or implied is made by RALI in this document, which is a technical data information sheet. The description of the product and its properties is for the sole purpose of identifying the product and does not constitute a warranty that the product or its properties shall conform to that description, nor is the description of the product and its properties a warranty by RALI that the goods are suitable for a particular purpose. Do not apply paint if relative humidity is above 85% or temperature is within 3 deg C of Dew Point being the MPT or Minimum Paint Temperature.



Technical Data Sheet

November 2015

This data sheet supersedes all previous issues

Always use correct Personal Protective Equipment

Surface Preparation



Old Finishes & Glass-Reinforced Plastics

Wash with C-Power diluted 20 parts clean water to 1 part C-Power. Degrease using the wipe on wipe off method using clean lint free cloths at all times with Wax & Grease Remover. Abrade with suitable grit paper; re-clean with Wax & Grease Remover. Ensure surface is completely dry and dust free before applying Rapid Filler.

Do not apply to existing finishes that are blistering, peeling, cracking, flaking or otherwise unsound.

Steel

Degrease thoroughly using the wipe on wipe off method using clean lint free cloths at all times with Wax & Grease Remover. Sand and eliminate all rust or corrosion (treat with Rust Kill). Wipe surface clean with Wax & Grease Remover. Dry then, within 20 minutes apply 81A Two-Pack Etch Primer (for optimum adhesion for large areas). Allow a minimum 3 hours (maximum 24 hours) flash time before applying Rapid Filler.

Aluminium

Degrease using the wipe on wipe off method using clean lint free cloths at all times with Wax & Grease Remover. Mechanically abrade with P280 or P320 disc. Treat with Hydrafos acid wash. Rinse with clean water, ensuring that all metal swarf and acid is removed dry. Immediately wipe surface clean with GP Thinners. Apply 81A 2-Pack Etch Primer within 20 minutes of surface preparation. Allow a minimum of a 3 hours flash time (24 hour maximum) before applying Rapid Filler.

Galvanised Steel

Degrease using the wipe on wipe off method using clean lint free cloths at all times with Wax & Grease Remover. Mechanically abrade to remove rust and corrosion. Treat with Hydrafos acid wash. Rinse with clean water. Immediately wipe surface clean with GP Thinners. Apply 81A 2-Pack Etch Primer within 20 minutes of surface preparation. Allow a minimum of a 3 hours flash time (24 hour maximum) before applying Rapid Filler.

Wood & MDF Board Composites

Clean thoroughly with Wax & Grease Remover using the wipe on wipe off method. Use clean lint free cloths at all times, and sand with fine grit paper. Remove dust and wipe clean with Wax & Grease Remover. Apply two full coats of Rapid Filler.

Plastic Bumpers

Clean thoroughly with Wax & Grease Remover using the wipe on wipe off method using clean lint free cloths at all times, sand with 320-grit paper. Remove dust and wipe clean with Wax & Grease Remover. Apply one full coat of Rapid Filler (adhesion problems can be encountered with some plastics, particularly if they have a 'waxy feel'. If in doubt check on a test area before proceeding).

Directions For Use

Mixing Ratio:

As Primer Filler

4:1:2 4 parts Rapid Filler

(Volume) 1 part General Purpose Hardener 2 parts 400 / 400 Slow

Reducer.

No warranty either expressed or implied is made by RALI in this document, which is a technical data information sheet. The description of the product and its properties is for the sole purpose of identifying the product and does not constitute a warranty that the product or its properties shall conform to that description, nor is the description of the product and its properties a warranty by RALI that the goods are suitable for a particular purpose. Do not apply paint if relative humidity is above 85% or temperature is within 3 deg C of Dew Point being the MPT or Minimum Paint Temperature.



November 2015

This data sheet supersedes all previous issues

Always use correct Personal Protective Equipment

Directions For Thinning:

Use cont.

As Primer Surfacer

4 parts Rapid Filler 4:1:4

1 part General Purpose Hardener to 4 parts 400 or 400 Slow

Strain before application. Apply 2 full coats with 5-10 minutes

flash-off between coats.

Remarks: Do not use activated primer beyond the pot-life time. Do not thin excessively to reduce to spraying viscosity after potlife time. Excessive film thickness can cause film defects such as cracking and poor through curing. Sand primer before topcoat is applied. RALI Rapid Filler cured with RALI Extra Fast 2K Hardener can be machine dry sanded sooner.

Note

Lower temperatures will slow drying; addition of up to 5% by volume of RALI 62C Accelerator to mixed primer and hardener will approximately halve curing and pot life times. Reduce addition to 1-2% when drying with IR lamps.

Misuse of RALI 62C Accelerator can cause loss of adhesion and poor flow-out.

Spray Compliant / Conventional Suction or Gravity Feed

Equipment: Air pressure: 275-380KPA (40-55 psi)

> Tip size: 1.5 - 1.8 mm



Health & Safety



For detailed information refer to Safety Data Sheet (SDS). Mixed product contains less than 0.1% isocyanate monomer H.D.I. When sprayed this product may be harmful by inhalation. Do not breathe vapour or spray. Avoid contact with skin and eyes. Wear suitable protective clothing, gloves, eye and face protection, including suitable breathing protection such as an air supplied respirator or hood.

Transport &

Storage

Sizes: **Dangerous Goods:** 1L. 4L 3A

UN:

1263

Hazchem:

Packing Group:

3[Y]E

Shipment name:

PAINT Flammable Liquid

Flash point:

4°C

No warranty either expressed or implied is made by RALI in this document, which is a technical data information sheet. The description of the product and its properties is for the sole purpose of identifying the product and does not constitute a warranty that the product or its properties shall conform to that description, nor is the description of the product and its properties a warranty by RALI that the goods are suitable for a particular purpose. Do not apply paint if relative humidity is above 85% or temperature is within 3 deg C of Dew Point being the MPT or Minimum Paint Temperature.